

LH964ex Climate Control

- Top- and Side Vent Control
- It is not possible to connect signals for extended control - such as Clock
- Hygostat
- Lee side signal
- Rain/Storm alarm
- Fire alarm

Industrivej 8
 DK-5471 Sønderø
 Denmark
 Tel: +45 64 89 22 11
 Fax: +45 64 89 33 11
 e-mail: dgtsales@senmatic.com
 www.senmatic.com

